Service Level

RIDGID

One World Technologies, Inc.

REPLACEMENT PARTS INFORMATION ONLY

SERVICE INFORMATION

Product

Ridgid Cordless Drill Model R82015, R83015, and R84015

Service Coverage

All above models with a date code prior to G0343.

Condition

Improvements to the motor and gear box assembly, has restricted the use of the original clutch and auxiliary handle components on these drill models manufactured prior to date code G0343. These models with a date code of G0343 and after are not affected.

Remedy

When replacing the motor and gear box assembly also replace the parts listed below using part numbers as indicated.

1. Auxiliary Handle Assembly	part 300188020
2. Spring Plate Holder	part 640670001
3. Clutch Pins (8)	part 680338010
4. Handle Mount	part 640664001
5. Handle Mount Screws (4)	part 660211028
Note: The clutch cap assembly, washers, spring, spring plate screws, and	
plastic sleeve will need to be transferred from	n the original gear box to the new
gear box.	

Submit warranty claim using	
Warranty claim compensation	Using Ridgid Labor Chart

For technical assistance, contact Ridgid Technical Support at 1-866-539-1710